


PTO Linkage NSN Correction



Dear Editor,

I'm a contractor in Kuwait, and we found an issue with the power takeoff (PTO) control assemblies for M939-series trucks.

TM 9-2320-272-24P-2 gives the same NSN for Item 13 of Fig 525 and Item 16 of Fig 528. The problem is that these are actually two different items.

We later learned the correct NSNs: Item 13 of Fig 525 is NSN 2590-01-083-1155 (PN 11669342-1) and Item 16 of Fig 528 is NSN 2590-01-106-2060 (PN 11669463).

Would you do me a favor and tell your readers about this correction? That will help out units and other contractors who run into this problem.

Mohammad Al-Ma'ani
Honeywell Contractor
Kuwait

Editor's note: Consider that favor done, Mr. Al-Ma'ani. Thanks for looking out for Soldiers.