


M1200 Armored Knight FSV, M707 Knight FSV, M7 BFIST & M1131 Stryker...

## Software Updates a Breeze on AKO

I'M NOT SURE IF THE SOFTWARE IN MY MISSION PROCESSOR UNIT (MPU) OR TARGETING STATION CONTROL PANEL (TSCP) IS UP-TO-DATE!

YOU CAN STOP SCRATCHING YOUR HEAD, SOLDIER!

THERE'S NOW A ONE-STOP AKO WEBSITE THAT LISTS THE MOST CURRENT SOFTWARE.



IF YOUR SOFTWARE HAPPENS TO BE OUT-OF-DATE, YOU CAN DOWNLOAD AND BURN THE NEW MISSION LOADER/VERIFIER (MLV) SOFTWARE FILES TO A CD FOR INSTALLATION ON YOUR MPU AND TSCP. JUST GO TO:  
<https://www.us.army.mil/suite/page/453627>

IF YOU CAN'T BURN CDS, YOU CAN GET THE SOFTWARE UPDATES BY CALLING DRS SUSTAINMENT SYSTEMS, INC.'S (DRS-SSI) BRAD NAUMER AT (314) 553-4082 OR EMAIL:  
[bnaumer@drs-ssi.com](mailto:bnaumer@drs-ssi.com)

QUESTIONS? CONTACT TACOM'S RICARDO HALL, DSN 786-4256, (586) 282-4256, OR EMAIL:  
[ricardo.j.hall4.civ@mail.mil](mailto:ricardo.j.hall4.civ@mail.mil)

